



### Motor Connection Diagrams 9 Leads

#### Across-the-Line Starting / Running Connections

Low Voltage Wye



High Voltage Wye



Switch L1 and L2 to reverse rotation