# Motor Connection Diagrams
## 12 Leads

Across-the-Line Starting / Running Connections

Low Voltage Delta




High Voltage Delta




Switch L1 and L2 to reverse rotation

Suitable for Wye–Delta Starting and Limited Part–Winding–Starting.
Please Contact Toshiba International for specific connections.