



Motor Connection Diagrams
12 Leads - CLOSED DELTA Connection
Single Voltage



Switch L1 and L2 to reverse rotation