

Motor Connection Diagram

12 Leads

Single Voltage



Switch L1 and L2 to reverse rotation