

# Motor Connection Diagram

## 12 Leads

## Single Voltage



Switch L1 and L2 to reverse rotation