



**Motor Connection Diagrams**  
12 Leads - CLOSED DELTA Connection  
Single Voltage



Switch L1 and L2 to reverse rotation